

Inspections: Damaged Pole Report

Service Request: 25-00915281 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 2400 BLOCK W. NORTHERN PKWY

Grid : 1050330 LLC: 7108

Descriptive Location and Comments:

Street: W. NORTHERN PKWY

Side of Street: N/S ✓ E/S _____ S/S _____ W/S _____

Pole location: 1st _____ 2nd _____ 3rd 3 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O _____ W/O ✓

Street or Landmark: PRECKNISS WAY

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated _____

11'6" _____

Aluminum ✓

Missing ✓

12' _____

Steel _____

Damaged _____

25' _____

Galvanized Steel _____

Arm/Fixture Missing _____

30' ✓

Fiberglass _____

Other _____

40' _____

Bolton Hill _____

Other _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head ✓

HPS Vapor _____

100 _____

6' ✓

Damaged _____

PMA _____

Mercury Vapor _____

150 _____

10' _____

Missing _____

Otterbein _____

Metal Halide _____

175 _____

15' _____

Homeland _____

LED ✓

200 _____

20' _____

Bolton Hill _____

Other _____

250 _____

Other _____

Victorian Acorn _____

400 ✓

Other _____

1000 _____

Pedestal Base:

Base Condition: Good _____ Bad: _____

Base Type:

Yes _____
No ✓

Bolts _____
Wires ✓
Conduit ✓

Metal _____
Concrete ✓

Date: 10-27-25 Inspector's Signature [Signature]

