

Inspections Damaged Pole Report

Service Request 25-00934655 Sector Gateway Primary

Location on Service Request: 1312 Southview Rd

Grid : 2030210 LLC: 7131

Descriptive Location and Comments:

Street: Havenwood Rd

Side of Street: N/S E/S S/S ✓ W/S

Pole location: 1" ✓ 2nd 3rd 4th 5th 6th Other

Direction : N/O E/O S/O W/O ✓

Street or Landmark: Southview Rd

Condition of Pole:

Deteriorated

Missing ✓

Damaged

Arm/Fixture Missing

Other

Pole Size :

11'6" ✓

12'

25'

30'

40'

Other

Type of Pole:

Aluminum

Steel ✓

Galvanized Steel

Fiberglass

Bolton Hill

Otterbein

Homeland

Wooden

Other

Fixture Type:

Cobra Head ✓

PMA

Otterbein

Homeland

Bolton Hill

Victorian Acorn

Other

Lamp Type:

HPS Vapor ✓

Mercury Vapor

Metal Halide

LED

Other

Wattage:

100

150 ✓

175

200

250

400

1000

Arm:

6'

10'

15'

20'

Other

Arm Condition:

Damaged

Missing

Pedestal Base:

Yes ✓

No

Base Condition:

Good

Bad:

Base Type:

Metal ✓

Concrete


Bolts ✓

Wires ✓

Conduit

Date: 11/3/2025 Inspector's Signature: T. Blackman

NEEDS
NEW
BASE



Steel
PMA
HPS