

Inspections: Damaged Pole Report

Service Request 25-00945105 Sector Gateway Primary

Location on Service Request: 2413 Fleetwood Ave

Grid : 2050320 LLC: 7072

Descriptive Location and Comments:

Street: Fleetwood

Side of Street: N/S E/S S/S ✓ W/S

Pole location: 1st 2nd ✓ 3rd 4th 5th 6th Other

Direction : N/O E/O S/O W/O ✓

Street or Landmark: Laurelton Ave

Condition of Pole:

Deteriorated ✓

Missing

Damaged

Arm/Fixture Missing

Other

NEEDS
New
Base

Pole Size :

11'6" ✓

12'

25'

30'

40'

Other

Type of Pole:

Aluminum

Steel ✓

Galvanized Steel

Fiberglass

Bolton Hill

Otterbein

Homeland

Wooden

Other

Fixture Type:

Cobra Head

PMA ✓

Otterbein

Homeland

Bolton Hill

Victorian Acorn

Other

Lamp Type:

HPS Vapor ✓

Mercury Vapor

Metal Halide

LED

Other

Wattage:

100

150 ✓

175

200

250

400

1000

Arm:

6'

10'

15'

20'

Other

Arm Condition:

Damaged

Missing

Pedestal Base:

Yes

No ✓

Base Condition:

Good

Bad:


Bolts
Wires ✓
Conduit

Base Type:

Metal

Concrete ✓

Date: 11/5/2025 Inspector's Signature: T. Blackman



PMA
HPS