

Inspections: Damaged Pole Report

Service Request 25-00953300 Sector 5610 Gateway Sanctuary Primary 4N

Location on Service Request: 5610 Sanctuary 4N

Grid : 2030530 LLC: 7170

Descriptive Location and Comments:

Street: Sanctuary 4N

Side of Street: N/S ✓ E/S ✓ S/S ✓ W/S ✓

Pole location: 1st ✓ 2nd ✓ 3rd ✓ 4th ✓ 5th ✓ 6th ✓ Other ✓

Direction : N/O ✓ E/O ✓ S/O ✓ W/O ✓

Street or Landmark: Denview Way

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated ✓

11'6"

Aluminum ✓

Missing ✓

12'

Steel ✓

Damaged ✓

25'

Galvanized Steel ✓

Arm/Fixture Missing ✓

30'

Fiberglass ✓

Other ✓

40'

Bolton Hill ✓

Other ✓

Otterbein ✓

Homeland ✓

Wooden ✓

Other ✓

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head ✓

HPS Vapor ✓

100 ✓

6' ✓

Damaged ✓

PMA ✓

Mercury Vapor ✓

150 ✓

10' ✓

Missing ✓

Otterbein ✓

Metal Halide ✓

175 ✓

15' ✓

Homeland ✓

LED ✓

200 ✓

20' ✓

Bolton Hill ✓

Other ✓

250 ✓

Other ✓

Victorian Acorn ✓

400 ✓

Other ✓

1000 ✓

Pedestal Base:

Base Condition:

Good

Bad:

Base Type:

Yes ✓

No ✓

Bolts ✓


Wires ✓

Conduit ✓

Metal ✓

Concrete ✓

Date: 11/6/2025 Inspector's Signature: T. Blackman



30 Foot Aluminum
pole
cobra head
LED