

Inspections: Damaged Pole Report

Service Request: 25-01000657 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 3316 Moravia Rd

Grid: 2030320 LLC: 7194

Descriptive Location and Comments:

Street: Moravia Rd

Side of Street: N/S _____ E/S ☒ S/S _____ W/S _____

Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction: N/O ☒ E/O _____ S/O _____ W/O _____

Street or Landmark: Harcourt Rd

Condition of Pole:

Deteriorated _____

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size:

11'6" _____

12' _____

25' ☒

30' _____

40' _____

Other _____

Type of Pole:

Aluminum ☒

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

NEEDS
New Base

Work Order #
19974681

Fixture Type:

Cobra Head ☒

PMA _____

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor _____

Mercury Vapor _____

Metal Halide _____

LED ☒

Other _____

Wattage:

100 _____

150 _____

175 _____

200 _____

250 ☒

400 _____

1000 _____

Arm:

6' ☒

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing ☒

Pedestal Base:

Yes ☒

No ☒

Base Condition:

Good

Bad:

Base Type:

Bolts

Wires

Conduit

☒

☒


☒

Metal

Concrete

☒

Date: 11/25/2025 Inspector's Signature: T. Blackman



25 Foot
Aluminum pole
cobra head
LED