

Inspections: Damaged Pole Report

Service Request: 25-01003985 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 25 N. Howard St
 Grid : 3010140 LLC: 6258

Descriptive Location and Comments:

Street: N. Howard St
 Side of Street: N/S _____ E/S ☒ S/S _____ W/S _____
 Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O _____ S/O ☒ W/O _____
 Street or Landmark: W. Fayette St

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated ☐

11'6" ☐

Aluminum ☐

Missing ☒

12' ☒

Steel ☐

Damaged ☐

25' ☐

Galvanized Steel ☐

Arm/Fixture Missing ☐

30' ☐

Fiberglass ☐

Other ☐

40' ☐

Bolton Hill ☐

Other ☐

Otterbein ☒

Homeland ☐

Wooden ☐

Other ☐

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head ☐

HPS Vapor ☐

100 ☐

6' ☐

Damaged ☐

PMA ☐

Mercury Vapor ☐

150 ☒

10' ☐

Missing ☐

Otterbein ☐

Metal Halide ☒

175 ☐

15' ☐

Homeland ☐

LED ☒

200 ☐

20' ☐

Bolton Hill ☐

Other ☐

250 ☐

Other ☐

Victorian Acorn ☒

400 ☐

Other ☐

1000 ☐

Pedestal Base:

Base Condition:

Good

Bad:


Base Type:

Yes ☐
No ☒

Bolts ☒
Wires ☒
Conduit ☒

Metal ☒
Concrete ☐

Date: 11/28/2025 Inspector's Signature: T. Blackman



Otterbein
Acorn Fixture