

Inspections: Damaged Pole Report

Service Request: 25 01043804 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 3610 Clifton Ave
 Grid : 1010420 LLC: 7087

Descriptive Location and Comments:

Street: Clifton Ave
 Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____
 Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O ☒ S/O _____ W/O _____
 Street or Landmark: Allendale Ave

Condition of Pole:

Deteriorated _____
 Missing ☒
 Damaged _____
 Arm/Fixture Missing _____
 Other _____

Pole Size :

11'6" _____
 12' _____
 25' ☒
 30' _____
 40' _____
 Other _____

Type of Pole:

Aluminum ☒
 Steel _____
 Galvanized Steel _____
 Fiberglass _____
 Bolton Hill _____
 Otterbein _____
 Homeland _____
 Wooden _____
 Other _____

Fixture Type:

Cobra Head ☒
 PMA _____
 Otterbein _____
 Homeland _____
 Bolton Hill _____
 Victorian Acorn _____
 Other _____

Lamp Type:

HPS Vapor _____
 Mercury Vapor _____
 Metal Halide _____
 LED ☒
 Other _____

Wattage:

100 _____
 150 _____
 175 _____
 200 _____
 250 _____
 400 ☒
 1000 _____

Arm:

6' ☒
 10' _____
 15' _____
 20' _____
 Other _____

Arm Condition:

Damaged _____
 Missing _____

Pedestal Base:

Yes _____
 No _____

Base Condition:

Bolts ☒
 Wires ☒
 Conduit ☒

Good


☒
☒
☒

Bad:

Base Type:

Metal ☒
 Concrete _____

Date: 12/17/2025 Inspector's Signature: G. Crowder 8512



254 CHLED

Service Request Summary Report
25-01043804
Printed Date: Dec 18, 2025 - 8:00:33 AM

Type: BGE-StLight Pole Installation
Created By: citizen Site Guest User
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 25-01043804
Priority: Standard
Status: Pending
Status Date: Dec 18, 2025 7:54:09 AM
Created Date: Dec 12, 2025 6:39:49 AM
Overdue on: Feb 13, 2026 4:08:53 PM
Closed on:

Location: 3610 CLIFTON AVE, Baltimore City, 21216
Location Details: It was removed Aug 1, 2025 case number 653020 and never replaced. It's dark on the street
Description: Don't know if it's city or BGE maintained. Called the city to get it fixed when it was laying on the ground and it was removed immediately but not replaced

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
Kathryn Baker		kbakernasb@gmail.com	+1 (443) 742-2213

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		12/18/2025 7:54 AM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1010420
Assign inspector	LLC / POLE #	7087
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	25 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report was created by G Crowder-12-17-25	Gregory Crowder	12/18/2025 7:56 AM	Private