

Inspections: Damaged Pole Report

Service Request **25-01055928** S. tor. Gateway Priority
 Location on Service Request **Brown Ave & Joplin St**
 Grid : **4020530** LLC: **7085**

Descriptive Location and Comments:

Street:

Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O _____ W/O ☒

Street or Landmark: **Joplin St**

Condition of Pole:

Deteriorated _____

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" ☒

12' _____

25' _____

30' _____

40' _____

Other _____

Type of Pole:

Aluminum ☒

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Fixture Type:

Cobra Head ☒

PMA ☒

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor ☒

Mercury Vapor _____

Metal Halide _____

LED _____

Other _____

Wattage:

100 ☒

150 ☒

175 _____

250 _____

400 _____

1000 _____

Other _____

Arm:

6' _____

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes ☒

No _____

Base Condition:

Good ☒


Bad: ☒

Bolts ☒
 Wires ☒
 Conduit ☒

Base Type:

Metal ☒
 Concrete _____

Date: **12/18/2025** Inspector's Signature: **[Signature]**



PMA
HPS