

Inspection: Damaged Pole Report

Service Request 25-01056704 S to: Gateway Priority

Location on Service Request 951 Fell St

Grid : 4020210 LLC: 6326

Descriptive Location and Comments:

Street: Fell St

Side of Street: N/S E/S S/S ✓ W/S

Pole location: 1st 2nd ✓ 3rd 4th 5th 6th Other

Direction : N/O E/O S/O W/O ✓

Street or Landmark: 951 Fell St

Condition of Pole:

Deteriorated
Missing ✓
Damaged
Arm/Fixture Missing
Other

Pole Size :

11'6"
12' ✓
25'
30'
40'
Other

Type of Pole:

Aluminum
Steel
Galvanized Steel
Fiberglass
Bolton Hill
Otterbein ✓
Homeland
Wooden
Other

Fixture Type:

Cobra Head
PMA
Otterbein ✓
Homeland
Bolton Hill
Victorian Acorn
Other

Lamp Type:

HPS Vapor
Mercury Vapor
Metal Halide
LED
Other

Wattage:

100
150 ✓
175
250
400
1000
Other

Arm:

6'
10'
15'
20'
Other

Arm Condition:

Damaged
Missing

Pedestal Base:

Yes ✓
No

Base Condition:

Bolts ✓
Wires ✓
Conduit ✓

Good

Bad:


Base Type:

Metal ✓
Concrete

Date: 12/23/2025

Inspector's Signature

[Signature]



Off the beaten path
of urban fixture