

Inspections Damaged Pole Report

Service Request **25-01084304** S to: Gateway Priority
 Location on Service Request **3415 Hudson St**
 Grid : **4020320** LLC: **7085**

Descriptive Location and Comments:

Street: **Hudson St**
 Side of Street: N/S ☒ E/S ☐ S/S ☒ W/S ☐
 Pole location: 1st ☒ 2nd ☐ 3rd ☐ 4th ☐ 5th ☐ 6th ☐ Other ☐
 Direction : N/O ☐ E/O ☒ S/O ☐ W/O ☐
 Street or Landmark: **So Highland**

Condition of Pole:

Deteriorated ☒
 Missing ☒
 Damaged ☐
 Arm/Fixture Missing ☐
 Other ☐

Pole Size :

11'6" ☐
 12' ☐
 25' ☒
 30' ☐
 40' ☐
 Other ☐

Type of Pole:

Aluminum ☒
 Steel ☐
 Galvanized Steel ☐
 Fiberglass ☐
 Bolton Hill ☐
 Otterbein ☐
 Homeland ☐
 Wooden ☐
 Other ☐

**NEEDS
New Base**

Fixture Type:

Cobra Head ☒
 PMA ☐
 Otterbein ☐
 Homeland ☐
 Bolton Hill ☐
 Victorian Acorn ☐
 Other ☐

Lamp Type:

HPS Vapor ☐
 Mercury Vapor ☐
 Metal Halide ☒
 LED ☒
 Other ☐

Wattage:

100 ☐
 150 ☐
 175 ☐
 250 ☒
 400 ☐
 1000 ☐
 Other ☐

Arm:

6' ☒
 10' ☐
 15' ☐
 20' ☐
 Other ☐

Arm Condition:

Damaged ☐
 Missing ☒

Pedestal Base:

Yes ☒
 No ☐


Base Condition:

Good ☒
 Bad: ☒
 Bolts ☒
 Wires ☒
 Conduit ☒

Base Type:

Metal ☒
 Concrete ☐

Date: **12/30/2025** Inspector's Signature: **[Signature]**



25 Foot Aluminum
pole
Cobra Head
LED