

Inspections: Damaged Pole Report

Service Request: 25-00964606 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 3700 Tudor Arms Ave
 Grid : 1030130 LLC: 7166

Descriptive Location and Comments:

Street: Tudor Arms Ave
 Side of Street: N/S _____ E/S _____ S/S _____ W/S ☒
 Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O _____ S/O ☒ W/O _____
 Street or Landmark: W. 37th St

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated _____

11'6" _____

Aluminum ☒

Missing ☒

12' ☒

Steel _____

Damaged _____

25' _____

Galvanized Steel _____

Arm/Fixture Missing _____

30' _____

Fiberglass _____

Other _____

40' _____

Bolton Hill _____

Other _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Need new base

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head _____

HPS Vapor _____

100 _____

6' _____

Damaged _____

PMA ☒

Mercury Vapor _____

150 ☒

10' _____

Missing _____

Otterbein _____

Metal Halide _____

175 _____

15' _____

Homeland _____

LED ☒

200 _____

20' _____

Bolton Hill _____

Other _____

250 _____

Other _____

Victorian Acorn _____

400 _____

Other _____

1000 _____

Pedestal Base:

Base Condition: Good _____ Bad: _____


Base Type:

Yes _____
No ☒

Bolts ☒
Wires ☒
Conduit ☒

Metal ☒
Concrete _____

Date: 11/13/2025 Inspector's Signature: G. Crowder 8512



the 11th PMT CED

Service Request Summary Report
25-00964606
Printed Date: Nov 13, 2025 - 4:00:11 PM

Type: BGE-StLight Pole Installation
Created By: citizen Site Guest User
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 25-00964606
Priority: Standard
Status: Pending
Status Date: Nov 13, 2025 3:53:40 PM
Created Date: Nov 11, 2025 4:39:25 PM
Overdue on: Jan 14, 2026 3:44:41 PM
Closed on:

Location: 3700 TUDOR ARMS AVE, Baltimore City, 21211
Location Details: Corner of W 37th and Tudor Arms Ave 21211
Description: Pole was hit by a car traveling the wrong way on a one way street. Pole Already had a dent at the bottom and went over when hit by the car

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
Joselin Martin		joselin97@hotmail.com	+1 (443) 416-1156

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		11/13/2025 3:53 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1030130
Assign inspector	LLC / POLE #	7166
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Steel/Aluminum Pole
Assign inspector	Type of Fixture	PMA
Assign inspector	Wattage of the Fixture	150 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : DPR Created By G Crowder-11-13-25	Gregory Crowder	11/13/2025 4:00 PM	Private