

Inspections: Damaged Pole Report

Service Request: 26-00013463 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: E. 33rd St & The Alameda

Grid : 2030230 LLC: 7149

Descriptive Location and Comments:

Street: E. 33rd St

Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O _____ W/O ☒

Street or Landmark: The Alameda

Condition of Pole:

Deteriorated _____
Missing ☒
Damaged _____
Arm/Fixture Missing _____
Other _____

Pole Size :

11'6" _____
12' _____
25' _____
30' ☒
40' _____
Other _____

Type of Pole:

Aluminum ☒
Steel _____
Galvanized Steel _____
Fiberglass _____
Bolton Hill _____
Otterbein _____
Homeland _____
Wooden _____
Other _____

NEEDS
pedestal
base

Fixture Type:

Cobra Head ☒
PMA _____
Otterbein _____
Homeland _____
Bolton Hill _____
Victorian Acorn _____
Other _____

Lamp Type:

HPS Vapor _____
Mercury Vapor _____
Metal Halide _____
LED ☒
Other _____

Wattage:

100 _____
150 _____
175 _____
200 _____
250 _____
400 ☒
1000 _____

Arm:

6' ☒
10' _____
15' _____
20' _____
Other _____

Arm Condition:

Damaged _____
Missing ☒

Pedestal Base:

Yes ☒
No ☒

Base Condition:

Bolts ☒
Wires ☒
Conduit ☒

Good

☒
☒
☒

Bad:

Base Type:

Metal ☒
Concrete ☒

Date: 1/8/2026 Inspector's Signature: T. Blackman

