

Inspections: Damaged Pole Report

Service Request: 26-00017221 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 205 Southway

Grid : 2030130 LLC: 7398

Descriptive Location and Comments:

Street: Southway

Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____

Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O ☒ S/O _____ W/O _____

Street or Landmark: CHANCERY Rd

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated ☒

11'6" ☒

Aluminum _____

Missing ☒

12' ☒

Steel _____

Damaged _____

25' _____

Galvanized Steel _____

Arm/Fixture Missing _____

30' _____

Fiberglass _____

Other _____

40' _____

Bolton Hill _____

Other _____

Otterbein _____

Homeland ☒

Wooden _____

Other _____

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head _____

HPS Vapor ☒

100 ☒

6' _____

Damaged _____

PMA _____

Mercury Vapor _____

150 ☒

10' _____

Missing _____

Otterbein ☒

Metal Halide _____

175 _____

15' _____

Homeland ☒

LED _____

200 _____

20' _____

Bolton Hill _____

Other _____

250 _____

Other _____

Victorian Acorn _____

400 _____

Other _____

1000 _____

Pedestal Base:

Base Condition:

Good

Bad:

Base Type:

Yes _____

Bolts

☒

Metal

No _____

Wires


☒

Concrete

Conduit

☒

Date: 1/9/2026 Inspector's Signature: T. Blackman



Home land pole
Home land Fixture