

Waiting on Frank

1/15/26

Inspections: Damaged Pole Report

Service Request: 26-00040594 Sector: 2 Gateway: _____ Primary: _____Location on Service Request: N. Rosedale St @ BloomingdaleGrid : 10 10 310 LLC: 7107

Descriptive Location and Comments:

Street: N. Rosedale StSide of Street: N/S _____ E/S ☒ S/S _____ W/S _____Pole location: 1st ☒ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____Direction : N/O ☒ E/O _____ S/O _____ W/O _____Street or Landmark: Bloomingdale

Condition of Pole:

Deteriorated _____

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" _____

12' _____

25' ☒

30' _____

40' _____

Other _____

Type of Pole:

Aluminum ☒

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Fixture Type:

Cobra Head ☒

PMA _____

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor _____

Mercury Vapor _____

Metal Halide ☒

LED _____

Other _____

Wattage:

100 _____

150 _____

175 _____

250 _____

400 _____

1000 _____

Other 200

Arm:

6' ☒

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes ☒

No _____

Base Condition:

Good ☒

Bad: _____

Bolts ☒Wires ☒Conduit ☒

Base Type:

Metal ☒

Concrete _____

Date: 1/15/2024 Inspector's Signature: J. Crowder - 8512

Service Request Summary Report
26-00040594
Printed Date: Jan 21, 2026 - 8:25:35 AM

Type: BGE-StLight Pole Installation
Created By: Gregory Crowder
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 26-00040594
Priority: Standard
Status: Pending
Status Date: Jan 21, 2026 8:19:12 AM
Created Date: Jan 15, 2026 3:33:58 PM
Overdue on: Mar 20, 2026 4:33:57 PM
Closed on:

Location: N ROSEDALE ST & BLOOMINGDALE RD, BC,
21216
Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		1/21/2026 8:20 AM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1010310
Assign inspector	LLC / POLE #	7107
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	25 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	Other
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created on 1-15-26	Gregory Crowder	1/21/2026 8:25 AM	Private
Assign inspector : missing pole report created on 1-15-26	Gregory Crowder	1/21/2026 8:25 AM	Public