

Inspections: Damaged Pole Report

Service Request: 26-00041678 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 513 PARK Ave
 Grid : 3010120 LLC: 6261

Descriptive Location and Comments:

Street: PARK Ave
 Side of Street: N/S _____ E/S ☒ S/S _____ W/S _____
 Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O _____ S/O ☒ W/O _____
 Street or Landmark: W. Centre St

Condition of Pole:

Deteriorated _____
 Missing ☒
 Damaged _____
 Arm/Fixture Missing _____
 Other _____

Pole Size :

11'6" _____
 12' ☒
 25' _____
 30' _____
 40' _____
 Other _____

Type of Pole:

Aluminum _____
 Steel _____
 Galvanized Steel _____
 Fiberglass _____
 Bolton Hill _____
 Otterbein _____
 Homeland ☒
 Wooden _____
 Other _____

Need new base

Fixture Type:

Cobra Head _____
 PMA _____
 Otterbein _____
 Homeland _____
 Bolton Hill _____
 Victorian Acorn ☒
 Other _____

Lamp Type:

HPS Vapor ☒
 Mercury Vapor _____
 Metal Halide _____
 LED _____
 Other _____

Wattage:

100 _____
 150 ☒
 175 _____
 200 _____
 250 _____
 400 _____
 1000 _____

Arm:

6' _____
 10' _____
 15' _____
 20' _____
 Other _____

Arm Condition:

Damaged _____
 Missing _____

Pedestal Base:

Yes _____
 No ☒

Base Condition:

Bolts _____
 Wires _____
 Conduit _____

Good


☒
☒
☒

Bad:

Base Type:

Metal _____
 Concrete ☒

Date: 1/21/2026 Inspector's Signature: G. Crowder 8512



Service Request Summary Report
26-00041078
Printed Date: Jan 21, 2026 - 2:52:47 PM

Type: BGE-StLight Pole Installation
Created By: Marcella Labellarte
Service Request Owner: BGE
Method Received: API
SLA Detail: 45 Business Days

SR #: 26-00041078
Priority: Standard
Status: Pending
Status Date: Jan 21, 2026 2:51:17 PM
Created Date: Jan 15, 2026 6:13:15 PM
Overdue on: Mar 20, 2026 4:36:44 PM
Closed on:

Location: 513 PARK AVE, Baltimore City,
21201
Location Details: Lamppost in front of Unity Bar
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
Marcella Labellarte		malabellarte@gmail.com	+1 (443) 253-3043

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		1/21/2026 2:51 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	3010120
Assign inspector	LLC / POLE #	6261
Assign inspector	BGE ASS Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Homeland Plc
Assign inspector	Type of Fixture	Acorn
Assign inspector	Wattage of the Fixture	150 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created by G Crowder-1-21-26	Gregory Crowder	1/21/2026 2:52 PM	Private