

Inspections: Damaged Pole Report

Service Request: 20-00041170 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 4506 HAZELWOOD AVE

Grid : 2030510 LLC: 7262

Descriptive Location and Comments:

Street: HAZELWOOD

Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____

Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O ☒ S/O _____ W/O _____

Street or Landmark: Hampton Ave

Condition of Pole:

Deteriorated ☐

Missing ☒

Damaged ☐

Arm/Fixture Missing ☐

Other _____

Pole Size :

11'6" _____

12' _____

25' ☒

30' _____

40' _____

Other _____

Type of Pole:

Aluminum ☐

Steel ☒

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Fixture Type:

Cobra Head ☒

PMA _____

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor _____

Mercury Vapor _____

Metal Halide _____

LED ☒

Other _____

Wattage:

100 _____

150 _____

175 _____

200 _____

250 ☒

400 _____

1000 _____

Arm:

6' ☒

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged ☐

Missing ☒

Pedestal Base:

Yes ☒

No ☐

Base Condition:

Good ☒

Bad: _____


Base Type:

Metal ☒

Concrete _____

Date: 1/21/2026 Inspector's Signature: T. Blackman

NEEDS
New
Base



25 Foot
Steel pole
Cobra Head
HPS