

Inspections: Damaged Pole Report

Service Request: 26-00045823 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 20 E. Fitting St

Grid: 4020130 LLC: 7449

Descriptive Location and Comments:

Street: Fitting St

Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction: N/O _____ E/O _____ S/O _____ W/O ☒

Street or Landmark: Marshall St

Condition of Pole:

Deteriorated ☒

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size:

11'6" ☒

12' _____

25' _____

30' _____

40' _____

Other _____

Work Order #
20563310

Type of Pole:

Aluminum ☒

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Fixture Type:

Cobra Head ☒

PMA ☒

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor _____

Mercury Vapor _____

Metal Halide ☒

LED ☒

Other _____

Wattage:

100 _____

150 ☒

175 _____

200 _____

250 _____

400 _____

1000 _____

Arm:

6' _____

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes _____
No _____


Base Condition:

Good _____
Bad _____
Bolts _____
Wires _____
Conduit _____

Base Type:

Metal _____
Concrete _____

Date: 1/21/2026 Inspector's Signature: T. Blackman



PMA
Town guide
Fixture