

Inspections: Damaged Pole Report

Service Request: 26-00146099 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 6437 Eastern Ave
 Grid : 4010530 LLC: 7225

Descriptive Location and Comments:

Street: Kanawha
 Side of Street: N/S _____ E/S ☒ S/S _____ W/S _____
 Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O _____ S/O ☒ W/O _____
 Street or Landmark: Eastern Ave

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated _____
 Missing ☒
 Damaged _____
 Arm/Fixture Missing _____
 Other _____

11'6" _____
 12' _____
 25' _____
 30' ☒
 40' _____

Aluminum ☒
 Steel _____
 Galvanized Steel _____
 Fiberglass _____
 Bolton Hill _____
 Otterbein _____
 Homeland _____
 Wooden _____
 Other _____

Work Order #
 20774480

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head ☒
 PMA _____
 Otterbein _____
 Homeland _____
 Bolton Hill _____
 Victorian Acorn _____
 Other _____

HPS Vapor _____
 Mercury Vapor _____
 Metal Halide _____
 LED ☒
 Other _____

100 _____
 150 _____
 175 _____
 200 _____
 250 _____
 400 ☒
 1000 _____

6' ☒
 10' _____
 15' _____
 20' _____
 Other _____

Damaged _____
 Missing ☒

Pedestal Base:

Base Condition:

Good

Bad:

Base Type:

Yes ☒
 No _____

Bolts ☒
 Wires ☒
 Conduit ☒

Metal ☒
 Concrete ☒

Date: 2/13/2026 Inspector's Signature: T. Blackman

30 Foot Aluminum Cobalt Head

Loading of assets and metadata at this location has been completed. Click on the icons to see their information

