

# Inspections: Damaged Pole Report

Service Request 26-08102522 Sector: \_\_\_\_\_ Gateway: \_\_\_\_\_ Primary: \_\_\_\_\_

Location on Service Request: 200 No Calvert St

Grid : 4010110 LLC: 7516

## Descriptive Location and Comments:

Street: Calvert St

Side of Street: N/S \_\_\_\_\_ E/S \_\_\_\_\_ S/S \_\_\_\_\_ W/S ☒

Pole location: 1<sup>st</sup> ☒ 2<sup>nd</sup> \_\_\_\_\_ 3<sup>rd</sup> \_\_\_\_\_ 4<sup>th</sup> \_\_\_\_\_ 5<sup>th</sup> \_\_\_\_\_ 6<sup>th</sup> \_\_\_\_\_ Other \_\_\_\_\_

Direction : N/O ☒ E/O \_\_\_\_\_ S/O \_\_\_\_\_ W/O \_\_\_\_\_

Street or Landmark: Dark Ln

## Condition of Pole:

Deteriorated ☒

Missing ☒

Damaged \_\_\_\_\_

Arm/Fixture Missing \_\_\_\_\_

Other \_\_\_\_\_

## Pole Size :

11'6" \_\_\_\_\_

12' \_\_\_\_\_

25' \_\_\_\_\_

30' ☒

40' \_\_\_\_\_

Other \_\_\_\_\_

## Type of Pole:

Aluminum ☒

Steel \_\_\_\_\_

Galvanized Steel \_\_\_\_\_

Fiberglass \_\_\_\_\_

Bolton Hill \_\_\_\_\_

Otterbein \_\_\_\_\_

Homeland \_\_\_\_\_

Wooden \_\_\_\_\_

Other \_\_\_\_\_

NEEDS  
New  
pedestal  
base

Work order #  
20754231

## Fixture Type:

Cobra Head ☒

PMA \_\_\_\_\_

Otterbein \_\_\_\_\_

Homeland \_\_\_\_\_

Bolton Hill \_\_\_\_\_

Victorian Acorn \_\_\_\_\_

Other \_\_\_\_\_

## Lamp Type:

HPS Vapor \_\_\_\_\_

Mercury Vapor \_\_\_\_\_

Metal Halide ☒

LED ☒

Other \_\_\_\_\_

## Wattage:

100 \_\_\_\_\_

150 \_\_\_\_\_

175 \_\_\_\_\_

200 \_\_\_\_\_

250 \_\_\_\_\_

400 ☒

1000 \_\_\_\_\_

## Arm:

6' ☒

10' \_\_\_\_\_

15' \_\_\_\_\_

20' \_\_\_\_\_

Other \_\_\_\_\_

## Arm Condition:

Damaged \_\_\_\_\_

Missing ☒

## Pedestal Base:

Yes ☒

No \_\_\_\_\_

## Base Condition:

Good

☒

☒

☒

Bad:

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

## Base Type:

Metal \_\_\_\_\_

Concrete ☒

Date: 2/15/2026 Inspector's Signature: T. Blackman

30 Foot Aluminum Cobra Head

