

Inspections: Damaged Pole Report

Service Request: 26-00128C14 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: E. RANDALL ST & WILLIAM ST

Grid : 4020130 LLC: 7248

Descriptive Location and Comments:

Street: E. RANDALL ST

Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O ☒ S/O _____ W/O _____

Street or Landmark: WILLIAM ST

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated _____

11'6" _____

Aluminum ☒

Missing ☒

12' _____

Steel _____

Damaged _____

25' ☒

Galvanized Steel _____

Arm/Fixture Missing _____

30' _____

Fiberglass _____

Other _____

40' _____

Bolton Hill _____

Other _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

wo# 20771267

NEEDS NEW BASE

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head ☒

HPS Vapor _____

100 _____

6' ☒

Damaged _____

PMA _____

Mercury Vapor _____

150 _____

10' _____

Missing _____

Otterbein _____

Metal Halide _____

175 _____

15' _____

Homeland _____

LED ☒

200 ☒

20' _____

Bolton Hill _____

Other _____

250 _____

Other _____

Victorian Acorn _____

400 _____

Other _____

1000 _____

Pedestal Base:

Base Condition:

Good

Bad:

Base Type:

Yes

No ☒

Bolts

Wires

Conduit

☒

☒

Metal

Concrete

☒

Date: 2-17-26 Inspector's Signature [Signature]

