

Inspections: Damaged Pole Report

Service Request: 26-00159935 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 208 E Cold Spring Ln

Grid : 2040130 LLC: 7189

Descriptive Location and Comments:

Street: E Cold Spring Ln

Side of Street: N/S _____ E/S 1 S/S ✓ W/S _____

Pole location: 1st _____ 2nd ✓ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O _____ W/O ✓

Street or Landmark: Kerneway

Condition of Pole:

Deteriorated _____
Missing ✓
Damaged _____
Arm/Fixture Missing _____
Other _____

Pole Size :

11'6" _____
12' _____
25' ✓
30' _____
40' _____
Other _____

Type of Pole:

Aluminum ✓
Steel _____
Galvanized Steel _____
Fiberglass _____
Bolton Hill _____
Otterbein _____
Homeland _____
Wooden _____
Other _____

Need new base

Fixture Type:

Cobra Head ✓
PMA _____
Otterbein _____
Homeland _____
Bolton Hill _____
Victorian Acorn _____
Other _____

Lamp Type:

HPS Vapor _____
Mercury Vapor _____
Metal Halide ✓
LED ✓
Other _____

Wattage:

100 _____
150 _____
175 _____
200 _____
250 ✓
400 ✓
1000 _____

Arm:

6' ✓
10' _____
15' _____
20' _____
Other _____

Arm Condition:

Damaged _____
Missing _____

Pedestal Base:

Yes ✓
No ✓

Base Condition:

Bolts
Wires
Conduit

Good

✓
✓
✓

Bad:

Base Type:

Metal ✓
Concrete _____

Date: 2/18/2026 Inspector's Signature: G. Crowder 8512



200
E. Cold Spring Ln

There are no known outages for this light.

DOWNED POLE & EXPOSED WIRES

If you discover a downed streetlight pole, exposed electrical wires or any other hazardous situation, please call us immediately at **1-800-665-0123** with the closest address, intersection or landmark.

NEVER TOUCH EXPOSED WIRES!

Pole Number

20401307159

REPORT THIS LIGHT

Service Request Summary Report
26-00159935
Printed Date: Feb 18, 2026 - 3:22:12 PM

Type: BGE-StLight Pole Installation
Created By: citizen Site Guest User
Service Request Owner: BGE
Method Received: API
SLA Detail: 45 Business Days

SR #: 26-00159935
Priority: Urgent
Status: Pending
Status Date: Feb 18, 2026 3:20:26 PM
Created Date: Feb 16, 2026 10:45:37 AM
Overdue on: Apr 22, 2026 9:08:02 AM
Closed on:

Location: 208 E COLD SPRING LN, Baltimore City,
21212
Location Details: Across from 208 E Cold Spring
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
Clint Gardner		cpgardner@loyola.edu	+1 (410) 830-1806

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		2/18/2026 3:20 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	2040130
Assign inspector	LLC / POLE #	7159
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	25 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created by G Crowder-2-18-26	Gregory Crowder	2/18/2026 3:22 PM	Private
