

Inspections: Damaged Pole Report

Service Request: 26-00167799 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 2413 SAINT PAUL ST

Grid : 2020130 LLC: 6121

Descriptive Location and Comments:

Street: SAINT PAUL ST

Side of Street: N/S _____ E/S / S/S _____ W/S _____

Pole location: 1st _____ 2nd / 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O / E/O _____ S/O _____ W/O _____

Street or Landmark: E. 24TH ST

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated _____

11'6" _____

Aluminum _____

Missing /

12' /

Steel _____

Damaged _____

25' _____

Galvanized Steel _____

Arm/Fixture Missing _____

30' _____

Fiberglass _____

Other _____

40' _____

Bolton Hill _____

Other _____

Otterbein _____

Homeland /

Wooden _____

Other _____

WO# 20787252

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head _____

HPS Vapor _____

100 _____

6' _____

Damaged _____

PMA _____

Mercury Vapor _____

150 /

10' _____

Missing _____

Otterbein _____

Metal Halide /

175 _____

15' _____

Homeland _____

LED /

200 _____

20' _____

Bolton Hill _____

Other _____

250 _____

Other _____

Victorian Acorn /

400 _____

Other _____

1000 _____

Pedestal Base:

Base Condition:

Good

Bad:

Base Type:

Yes /

No _____

Bolts

Wires

Conduit

/

/

/

Metal

Concrete

/

/

Date: 2-19-26 Inspector's Signature [Signature]

