

Inspections: Damaged Pole Report

Service Request: ~~26-00204~~ ⁸⁶³ 26-00204 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 700 S. Bond St

Grid : 4010230 LLC: 7577

Descriptive Location and Comments:

Street: 700 S. Bond St

Side of Street: N/S _____ E/S _____ S/S _____ W/S ☒

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O ☒ W/O _____

Street or Landmark: Aliceanna St

Condition of Pole:

Deteriorated _____

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" ☒

12' ☒

25' _____

30' _____

40' _____

Other _____

Type of Pole:

Aluminum _____

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein ☒

Homeland _____

Wooden _____

Other _____

Fixture Type:

Cobra Head _____

PMA _____

Otterbein ☒

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor ☒

Mercury Vapor _____

Metal Halide _____

LED _____

Other _____

Wattage:

100 _____

150 ☒

175 _____

200 _____

250 _____

400 _____

1000 _____

Arm:

6' _____

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes _____

No ☒

Base Condition:

Good _____

Bad: _____

Bolts ☒

Wires ☒


Conduit ☒

Base Type:

Metal ☒

Concrete _____

Date: 3/4/2026 Inspector's Signature: T. Blackman



Otterbein
Otterbein
Fixtome