

Inspections: Damaged Pole Report

Service Request: **26-00204527** Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: **2200 HPghview**

Grid : **2020330** LLC: **7032**

Descriptive Location and Comments:

Street: **HPghview**

Side of Street: N/S _____ E/S _____ S/S _____ W/S ☒

Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O ☒ W/O _____

Street or Landmark: **Lyndale Ave**

Condition of Pole:

Deteriorated ☒

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" ☒

12' _____

25' _____

30' _____

40' _____

Other _____

Type of Pole:

Aluminum ☒

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Fixture Type:

Cobra Head ☒

PMA ☒

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor _____

Mercury Vapor _____

Metal Halide ☒

LED ☒

Other _____

Wattage:

100 ☒

150 ☒

175 _____

200 _____

250 _____

400 _____

1000 _____

Arm:

6' _____

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes ☒

No ☒

Base Condition:

Good ☒


Bad: _____

Base Type:

Metal ☒

Concrete _____

Date: **3/4/2026** Inspector's Signature: **T. Blackman**



PMA
LED