

Inspections: Damaged Pole Report

Service Request: 26-00245800 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 4709 Roland Ave
 Grid: 1040220 LLC: 7140

Descriptive Location and Comments:

Street: Roland Ave
 Side of Street: N/S _____ E/S ☒ S/S _____ W/S _____
 Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction: N/O ☒ E/O _____ S/O _____ W/O _____
 Street or Landmark: Club Rd

Condition of Pole:

Pole Size:

Type of Pole:

Deteriorated _____	11'6" _____	Aluminum _____
Missing ☒	12' ☒	Steel _____
Damaged _____	25' _____	Galvanized Steel _____
Arm/Fixture Missing _____	30' _____	Fiberglass _____
Other _____	40' _____	Bolton Hill _____
	Other _____	Otterbein ☒
		Homeland ☒
		Wooden _____
		Other _____

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head _____	HPS Vapor ☒	100 _____	6' _____	Damaged _____
PMA _____	Mercury Vapor _____	150 ☒	10' _____	Missing _____
Otterbein _____	Metal Halide _____	175 _____	15' _____	
Homeland _____	LED _____	200 _____	20' _____	
Bolton Hill _____	Other _____	250 _____	Other _____	
Victorian Acorn ☒		400 _____		
Other _____		1000 _____		

Pedestal Base:

Base Condition:

Good

Bad:

Base Type:

Yes ☒
 No _____

Bolts
 Wires
 Conduit

☒
☒
☒

Metal ☒
 Concrete _____

Date: 3/17/2026 Inspector's Signature: G. Crowder 8512

An aerial photograph of a residential neighborhood. The map shows several streets: Roland Ave running horizontally across the top, Church Ln running diagonally from the middle left to the bottom right, Woodlawn Rd running diagonally from the bottom left to the bottom right, and Upland Rd running vertically on the far right. Club Rd is visible at the top center. Numerous houses are scattered throughout the area, many with visible house numbers. A large, circular, white-outlined marker is centered on a house at the intersection of Church Ln and Woodlawn Rd. Several yellow circular markers with a white lightbulb icon are placed at various points along the streets and near houses. The terrain is mostly green with trees and some open grassy areas.

Woodlawn Rd

Service Request Summary Report
26-00245800
Printed Date: Mar 17, 2026 - 11:54:28 AM

Type: BGE-StLight Pole Installation
Created By: Tennille Gilliam
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 26-00245800
Priority: Standard
Status: Pending
Status Date: Mar 17, 2026 11:52:28 AM
Created Date: Mar 14, 2026 7:48:44 AM
Overdue on: May 18, 2026 1:15:13 PM
Closed on:

Location: 4709 ROLAND AVE, Baltimore City,
21210
Location Details:
Description: caller said there was a accident

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
gofrey jacobs			+1 (410) 889-7714

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		3/17/2026 11:52 AM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1040220
Assign inspector	LLC / POLE #	7140
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Homeland Ple
Assign inspector	Type of Fixture	Acom
Assign inspector	Wattage of the Fixture	150 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : MISSING POLE REPORT CREATED BY GCROWDER-3-17-26	Gregory Crowder	3/17/2026 11:54 AM	Private