

Inspections: Damaged Pole Report

Service Request 26-00248980 Sector _____ Gateway: _____ Primary: _____

Location on Service Request: 2310 E. Enger St

Grid : 2010240 LLC: 7104

Descriptive Location and Comments:

Street: Enger St

Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O ☒ E/O _____ S/O _____ W/O ☒

Street or Landmark: N. Bradford St

Condition of Pole:

Deteriorated ☒

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" ☒

12' _____

25' _____

30' _____

40' _____

Other _____

Type of Pole:

Aluminum ☒

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

**NEED NEW
BASE**

Fixture Type:

Cobra Head ☒

PMA ☒

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor _____

Mercury Vapor _____

Metal Halide _____

LED ☒

Other _____

Wattage:

100 _____

150 ☒

175 _____

200 _____

250 _____

400 _____

1000 _____

Arm:

6' _____

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes ☒
No ☒

Base Condition:

Bolts ☒
Wires ☒
Conduit ☒

Good


☒
☒
☒

Bad:

Base Type:

Metal ☒
Concrete _____

Date: 3/17/2026 Inspector's Signature: T. Blackman



PMA
CITY LED