

Inspections: Damaged Pole Report

Service Request 26-00251961 Sector _____ Gateway _____ Primary: _____

Location on Service Request: 5500 Leith Rd

Grid : 2050230 LLC: 7097

Descriptive Location and Comments:

Street: Cochran Ave

Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O _____ W/O ☒

Street or Landmark: Leith Rd

Condition of Pole:

Deteriorated _____

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" ☒

12' _____

25' _____

30' _____

40' _____

Other _____

Type of Pole:

Aluminum ☒

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Fixture Type:

Cobra Head _____

PMA ☒

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor _____

Mercury Vapor _____

Metal Halide ☒

LED ☒

Other _____

Wattage:

100 _____

150 ☒

175 _____

200 _____

250 _____

400 _____

1000 _____

Arm:

6' _____

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes ☒

No ☒

Base Condition:

Good _____

Bad _____

Bolts ☒

Wires ☒

Conduit ☒

Base Type:

Metal ☒

Concrete _____

Date: 3/17/2026 Inspector's Signature: T. Blackman

