

Inspections: Damaged Pole Report

Service Request 26-00282997 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 501 N. Calvert St

Grid: 4010110 LLC: 7504

Descriptive Location and Comments:

Street: Calvert St

Side of Street: N/S _____ E/S ☒ S/S _____ W/S _____

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction: N/O ☒ E/O _____ S/O _____ W/O _____

Street or Landmark: Franklin St

Condition of Pole:

Deteriorated ☒

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size:

11'6" _____

12' _____

25' _____

30' ☒

40' _____

Other _____

Type of Pole:

Aluminum ☒

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Fixture Type:

Cobra Head ☒

PMA _____

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor _____

Mercury Vapor _____

Metal Halide _____

LED ☒

Other _____

Wattage:

100 _____

150 _____

175 _____

200 _____

250 _____

400 ☒

1000 _____

Arm:

6' ☒

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing ☒

Pedestal Base:

Yes ☒
No _____

Base Condition:

Good

Bad:


Base Type:

Bolts ☒
Wires ☒
Conduit ☒

Metal ☒
Concrete ☒

Date: 3/30/2026 Inspector's Signature: T. Blackman

NEEDS
New
Pedestal
Base



30 Foot Aluminum
pole
Cove Neck
LED