

Inspections: Damaged Pole Report

Service Request 26-00247938 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 222 No Charles St

Grid : 3010120 LLC: 6412

Descriptive Location and Comments:

Street: W. Saratoga St

Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____

Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O _____ W/O ☒

Street or Landmark: No Charles St

Condition of Pole:

Deteriorated ☒

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" _____

12' ☒

25' _____

30' _____

40' _____

Other _____

Type of Pole:

Aluminum _____

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein ☒

Homeland _____

Wooden _____

Other _____

WORK order #
20876062

Fixture Type:

Cobra Head _____

PMA _____

Otterbein _____

Homeland _____

Bolton Hill ☒

Victorian Acorn ☒

Other _____

Lamp Type:

HPS Vapor _____

Mercury Vapor _____

Metal Halide ☒

LED ☒

Other _____

Wattage:

100 _____

150 ☒

175 _____

200 _____

250 _____

400 _____

1000 _____

Arm:

6' _____

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes _____
No _____

Base Condition:

Bolts _____
Wires _____
Conduit _____


Good _____

Bad _____

Base Type:

Metal _____
Concrete _____

Date: 4/12/2026 Inspector's Signature: T. Blackman



Otterbein
Acorn Fixture