

Inspections: Damaged Pole Report

Service Request 25-00497907 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 1126 BONSAL St

Grid : 4020420 LLC: 7088

Descriptive Location and Comments:

Street: BONSAL St

Side of Street: N/S _____ E/S _____ S/S _____ W/S ☒

Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O ☒ E/O _____ S/O _____ W/O _____

Street or Landmark: Toome St

Condition of Pole:

Deteriorated _____

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" ☒

12' _____

25' _____

30' _____

40' _____

Other _____

Type of Pole:

Aluminum ☒

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Fixture Type:

Cobra Head _____

PMA ☒

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor _____

Mercury Vapor _____

Metal Halide ☒

LED _____

Other _____

Wattage:

100 ☒

150 ☒

175 _____

200 _____

250 _____

400 _____

1000 _____

Arm:

6' _____

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes ☒
No _____

Base Condition:

Good _____


Bad: _____

Bolts ☒
Wires ☒
Conduit ☒

Base Type:

Metal ☒
Concrete _____

Date: 6/17/2025 Inspector's Signature: T. Blackman



PMA
BEE
LED