

Inspections: Damaged Pole Report

Service Request 26-00348225 Sector Gateway: Primary:

Location on Service Request: 5700 Eastern Ave

Grid : 4610440 LLC: 7231

Descriptive Location and Comments:

Street: Eastern Ave

Side of Street: N/S E/S S/S ✓ W/S

Pole location: 1" ✓ 2nd 3rd 4th 5th 6th Other

Direction : N/O E/O ✓ S/O W/O

Street or Landmark: Bayview Blvd

Condition of Pole:

Deteriorated ✓

Missing ✓

Damaged

Arm/Fixture Missing

Other

Pole Size :

11'6"

12'

25'

30' ✓

40'

Other

Type of Pole:

Aluminum ✓

Steel

Galvanized Steel

Fiberglass

Bolton Hill

Otterbein

Homeland

Wooden

Other

Fixture Type:

Cobra Head ✓

PMA

Otterbein

Homeland

Bolton Hill

Viktorian Acorn

Other

Lamp Type:

HPS Vapor

Mercury Vapor

Metal Halide

LED ✓

Other

Wattage:

100

150

175

200

250

400 ✓

1000

Arm:

6' ✓

10'

15'

20'

Other

Arm Condition:

Damaged

Missing ✓

Pedestal Base:

Yes
No ✓

Base Condition:

Good


Bad:

Base Type:

Bolts ✓
Wires ✓
Conduit ✓

Metal
Concrete ✓

Date: 4 / 20 / 2026 Inspector's Signature T. Blackman



30 Foot
Aluminum
pole
Cobra Head
LED