



42" RCP with flow
MSU24OUT00017


Unsure if this
manhole connects to
the flowing outfall.
Flow was observed
flowing north.

Flow in the manhole going N

Herring Run

Morgan State Campus Road

Legend

-  Inspected Outfalls
-  Non-NPDES Outfalls
-  Inlets
-  Manholes
-  Pipes