

Inspections: Damaged Pole Report

Service Request 26-00414424 Sector E-30th St & Hartford Rd Gateway Primary

Location on Service Request: E-30th St & Hartford Rd

Grid : 2020220 LLC: 7005

Descriptive Location and Comments:

Street: Hartford Rd

Side of Street: N/S E/S S/S W/S ✓

Pole location: 1st ✓ 2nd 3rd 4th 5th 6th Other

Direction : N/O E/O S/O ✓ W/O

Street or Landmark: 30th St

Condition of Pole:

Deteriorated
Missing ✓
Damaged
Arm/Fixture Missing
Other

Pole Size :

11'6"
12'
25'
30' ✓
40'
Other

Type of Pole:

Aluminum ✓
Steel
Galvanized Steel
Fiberglass
Bolton Hill
Otterbein
Homeland
Wooden
Other

NEEDS
New
Pedestal
Base

Work order #
20949310

Fixture Type:

Cobra Head ✓
PMA
Otterbein
Homeland
Bolton Hill
Victorian Acorn
Other

Lamp Type:

HPS Vapor
Mercury Vapor
Metal Halide
LED ✓
Other

Wattage:

100
150
175
200
250
400 ✓
1000

Arm:

6' ✓
10'
15'
20'
Other

Arm Condition:

Damaged
Missing ✓

Pedestal Base:

Yes ✓
No

Base Condition:

Good Bad
Bolts ✓
Wires
Conduit

Base Type:

Metal
Concrete ✓

Date: 5/17/2026 Inspector's Signature: T. Blackman

Report a Street Light Outage

https://bge-odnonmndjob.streetlightoutages.com/public/default.html

east 30th st & harford rd ballmore

STREETLIGHT DETAILS

We are aware of a problem on this streetlight.

Status: **Awaiting Diagnosis**

Pole Number: 20202207005

Order Number: 20949310

Date Reported: 4/29/2026 7:30 PM EDT

Estimated Time of Repair: 05/02/2026

DOWNED POLE & EXPOSED WIRES

If you discover a downed streetlight pole, exposed electrical wires or any other hazardous situation, please call us immediately at **1-800-685-0123** with the closest address, intersection or landmark.

NEVER TOUCH EXPOSED WIRES!

Subscribe to Incident Alerts

Enter your email. For multiple emails, separate with semicolon (;)

30 Foot Aluminum Pole
Cobra Head LED