

Inspections: Damaged Pole Report

Service Request: 26-00435240 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 1228 Eo Baltimore St

Grid : 4010120 LLC: 5003

Descriptive Location and Comments:

Street: Baltimore St

Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O _____ W/O ☒

Street or Landmark: Central Ave

Condition of Pole:

Deteriorated ☐

Missing ☒

Damaged ☐

Arm/Fixture Missing ☐

Other _____

Pole Size :

11'6" ☐

12' ☒

25' ☐

30' ☐

40' ☐

Other _____

Type of Pole:

Aluminum ☐

Steel ☐

Galvanized Steel ☐

Fiberglass ☐

Bolton Hill ☐

Otterbein ☐

Homeland ☒

Wooden ☐

Other _____

Fixture Type:

Cobra Head ☐

PMA ☐

Otterbein ☐

Homeland ☐

Bolton Hill ☐

Victorian Acorn ☒

Other _____

Lamp Type:

HPS Vapor ☒

Mercury Vapor ☐

Metal Halide ☐

LED ☐

Other ☐

Wattage:

100 ☐

150 ☒

175 ☐

200 ☐

250 ☐

400 ☐

1000 ☐

Arm:

6' ☐

10' ☐

15' ☐

20' ☐

Other ☐

Arm Condition:

Damaged ☐

Missing ☐

Pedestal Base:

Yes ☒
No ☐


Base Condition:

Good ☒
Bad: ☐
Bolts ☒
Wires ☒
Conduit ☒

Base Type:

Metal ☒
Concrete ☐

Date: 5 / 13 / 2026 Inspector's Signature: T. Blackman



Home Inwd
Acorn Fixture