

# Inspections: Damaged Pole Report

Service Request 26-00465223 Sector: \_\_\_\_\_ Gateway: \_\_\_\_\_ Primary: \_\_\_\_\_

Location on Service Request: 2900 Clifton Park Ter

Grid : 2020310 LLC: 7090

## Descriptive Location and Comments:

Street: Clifton Park Ter

Side of Street: N/S ☒ E/S \_\_\_\_\_ S/S \_\_\_\_\_ W/S \_\_\_\_\_

Pole location: 1<sup>st</sup> ☒ 2<sup>nd</sup> \_\_\_\_\_ 3<sup>rd</sup> \_\_\_\_\_ 4<sup>th</sup> \_\_\_\_\_ 5<sup>th</sup> \_\_\_\_\_ 6<sup>th</sup> \_\_\_\_\_ Other \_\_\_\_\_

Direction : N/O \_\_\_\_\_ E/O ☒ S/O \_\_\_\_\_ W/O \_\_\_\_\_

Street or Landmark: Clarence Ave

## Condition of Pole:

Deteriorated \_\_\_\_\_  
Missing ☒  
Damaged \_\_\_\_\_  
Arm/Fixture Missing \_\_\_\_\_  
Other \_\_\_\_\_

## Pole Size :

11'6" ☒  
12' \_\_\_\_\_  
25' \_\_\_\_\_  
30' \_\_\_\_\_  
40' \_\_\_\_\_  
Other \_\_\_\_\_

## Type of Pole:

Aluminum ☒  
Steel \_\_\_\_\_  
Galvanized Steel \_\_\_\_\_  
Fiberglass \_\_\_\_\_  
Bolton Hill \_\_\_\_\_  
Otterbein \_\_\_\_\_  
Homeland \_\_\_\_\_  
Wooden \_\_\_\_\_  
Other \_\_\_\_\_

NEEDS  
New  
Base

## Fixture Type:

Cobra Head \_\_\_\_\_  
PMA ☒  
Otterbein \_\_\_\_\_  
Homeland \_\_\_\_\_  
Bolton Hill \_\_\_\_\_  
Victorian Acorn \_\_\_\_\_  
Other \_\_\_\_\_

## Lamp Type:

HPS Vapor ☒  
Mercury Vapor \_\_\_\_\_  
Metal Halide \_\_\_\_\_  
LED \_\_\_\_\_  
Other \_\_\_\_\_

## Wattage:

100 \_\_\_\_\_  
150 ☒  
175 \_\_\_\_\_  
200 \_\_\_\_\_  
250 \_\_\_\_\_  
400 \_\_\_\_\_  
1000 \_\_\_\_\_

## Arm:

6' \_\_\_\_\_  
10' \_\_\_\_\_  
15' \_\_\_\_\_  
20' \_\_\_\_\_  
Other \_\_\_\_\_

## Arm Condition:

Damaged \_\_\_\_\_  
Missing \_\_\_\_\_

## Pedestal Base:

Yes \_\_\_\_\_  
No ☒

## Base Condition:

Good ☒  
Bad: ☒  
Bolts ☒  
Wires ☒  
Conduit ☒

## Base Type:

Metal ☒  
Concrete \_\_\_\_\_

Date: 5/21/2026 Inspector's Signature: T. Blackman



PMA  
HPS