

Inspections: Damaged Pole Report

Service Request: 26-00485721 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 5400 Relcrest Rd

Grid : 2020530 LLC: 6257

Descriptive Location and Comments:

Street: Relcrest Rd

Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____

Pole location: 1st _____ 2nd _____ 3rd ☒ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O ☒ S/O _____ W/O _____

Street or Landmark: Frankford Ave

Condition of Pole:

Deteriorated ☒
Missing ☒
Damaged _____
Arm/Fixture Missing _____
Other _____

Pole Size :

11'6" _____
12' ☒
25' _____
30' _____
40' _____
Other _____

Type of Pole:

Aluminum _____
Steel _____
Galvanized Steel _____
Fiberglass _____
Bolton Hill _____
Otterbein _____
Homeland ☒
Wooden _____
Other _____

NEEDS
new
base

Fixture Type:

Cobra Head _____
PMA _____
Otterbein _____
Homeland _____
Bolton Hill _____
Victorian Acorn ☒
Other _____

Lamp Type:

HPS Vapor ☒
Mercury Vapor _____
Metal Halide _____
LED _____
Other _____

Wattage:

100 _____
150 ☒
175 _____
200 _____
250 _____
400 _____
1000 _____

Arm:

6' _____
10' _____
15' _____
20' _____
Other _____

Arm Condition:

Damaged _____
Missing _____

Pedestal Base:

Yes ☒
No _____

Base Condition:

Good ☒
Bad: _____
Bolts ☒
Wires ☒
Conduit ☒

Base Type:

Metal ☒
Concrete _____

Date: 5/26/2026 Inspector's Signature: T. Blackman



Home and
Acorn
Fixture