

Inspections: Damaged Pole Report

Service Request 26-00491498 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 1600 Walterswood Rd

Grid : 2050240 LLC: 7136

Descriptive Location and Comments:

Street: Walterswood Rd

Side of Street: N/S _____ E/S ☒ S/S _____ W/S _____

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O ☒ W/O _____

Street or Landmark: Fenwick Ave

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated _____

11'6" ☒

Aluminum ☒

Missing ☒

12' _____

Steel _____

Damaged _____

25' _____

Galvanized Steel _____

Arm/Fixture Missing _____

30' _____

Fiberglass _____

Other _____

40' _____

Bolton Hill _____

Other _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head _____

HPS Vapor ☒

100 _____

6' _____

Damaged _____

PMA ☒

Mercury Vapor _____

150 ☒

10' _____

Missing _____

Otterbein _____

Metal Halide ☒

175 _____

15' _____

Homeland _____

LED ☒

200 _____

20' _____

Bolton Hill _____

Other _____

250 _____

Other _____

Victorian Acorn _____

400 _____

Other _____

1000 _____

Pedestal Base:

Base Condition:

Good _____

Bad: _____

Base Type:

Yes ☒

Bolts ☒

Metal ☒


No ☒

Wires ☒

Concrete ☒

Conduit ☒

Date: 6/1/2026 Inspector's Signature: T. Blackman



PMA
LED