

Inspections: Damaged Pole Report

Service Request: 26-00551459 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: NEWLAND Rd E Suffolk Rd

Grid : 2030130 LLC: 7325

Descriptive Location and Comments:

Street: Newland Rd

Side of Street: N/S _____ E/S _____ S/S _____ W/S ☒

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O ☒ W/O _____

Street or Landmark: Suffolk Rd

Condition of Pole:

Deteriorated _____
Missing ☒
Damaged _____
Arm/Fixture Missing _____
Other _____

Pole Size :

11'6" _____
12' ☒
25' _____
30' _____
40' _____
Other _____

Type of Pole:

Aluminum _____
Steel _____
Galvanized Steel _____
Fiberglass _____
Bolton Hill _____
Otterbein ☒
Homeland _____
Wooden _____
Other _____

Fixture Type:

Cobra Head _____
PMA _____
Otterbein _____
Homeland ☒
Bolton Hill _____
Victorian Acorn _____
Other _____

Lamp Type:

HPS Vapor ☒
Mercury Vapor _____
Metal Halide _____
LED _____
Other _____

Wattage:

100 _____
150 ☒
175 _____
200 _____
250 _____
400 _____
1000 _____

Arm:

6' _____
10' _____
15' _____
20' _____
Other _____

Arm Condition:

Damaged _____
Missing _____

Pedestal Base:

Yes _____
No ☒

Base Condition:

Bolts _____
Wires ☒
Conduit ☒

Good


☒
☒
☒

Bad:

Base Type:

Metal ☒
Concrete _____

Date: 6/16/2026 Inspector's Signature: T. Blackman



HomeLand
HomeLand Fixtune