

Inspections: Damaged Pole Report

Service Request: 26-00565562 Sector: \_\_\_\_\_ Gateway: \_\_\_\_\_ Primary: \_\_\_\_\_

Location on Service Request: 6100 Loch Raven Blvd

Grid : 2050220 LLC: 7022

Descriptive Location and Comments:

Street: Loch Raven Blvd

Side of Street: N/S \_\_\_\_\_ E/S ☒ S/S \_\_\_\_\_ W/S \_\_\_\_\_

Pole location: 1<sup>st</sup> \_\_\_\_\_ 2<sup>nd</sup> ☒ 3<sup>rd</sup> \_\_\_\_\_ 4<sup>th</sup> \_\_\_\_\_ 5<sup>th</sup> \_\_\_\_\_ 6<sup>th</sup> \_\_\_\_\_ Other \_\_\_\_\_

Direction : N/O \_\_\_\_\_ E/O \_\_\_\_\_ S/O ☒ W/O \_\_\_\_\_

Street or Landmark: Meridene dr

Condition of Pole:

Deteriorated \_\_\_\_\_  
Missing ☒  
Damaged \_\_\_\_\_  
Arm/Fixture Missing \_\_\_\_\_  
Other \_\_\_\_\_

Pole Size :

11'6" \_\_\_\_\_  
12' \_\_\_\_\_  
25' \_\_\_\_\_  
30' ☒  
40' \_\_\_\_\_  
Other \_\_\_\_\_

Type of Pole:

Aluminum ☒  
Steel \_\_\_\_\_  
Galvanized Steel \_\_\_\_\_  
Fiberglass \_\_\_\_\_  
Bolton Hill \_\_\_\_\_  
Otterbein \_\_\_\_\_  
Homeland \_\_\_\_\_  
Wooden \_\_\_\_\_  
Other \_\_\_\_\_

NEEDS  
New  
Pedestal  
Base

Fixture Type:

Cobra Head ☒  
PMA \_\_\_\_\_  
Otterbein \_\_\_\_\_  
Homeland \_\_\_\_\_  
Bolton Hill \_\_\_\_\_  
Victorian Acorn \_\_\_\_\_  
Other \_\_\_\_\_

Lamp Type:

HPS Vapor \_\_\_\_\_  
Mercury Vapor \_\_\_\_\_  
Metal Halide \_\_\_\_\_  
LED ☒  
Other \_\_\_\_\_

Wattage:

100 \_\_\_\_\_  
150 \_\_\_\_\_  
175 \_\_\_\_\_  
200 \_\_\_\_\_  
250 \_\_\_\_\_  
400 ☒  
1000 \_\_\_\_\_

Arm:

6' ☒  
10' \_\_\_\_\_  
15' \_\_\_\_\_  
20' \_\_\_\_\_  
Other \_\_\_\_\_

Arm Condition:

Damaged \_\_\_\_\_  
Missing ☒

Pedestal Base:

Yes ☒  
No \_\_\_\_\_

Base Condition:

Bolts  
Wires  
Conduit

Good:


☒  
☒  
☒

Bad:

Base Type:

Metal \_\_\_\_\_  
Concrete ☒

Date: 6/17/2026 Inspector's Signature: T. Blackman



30 Foot Aluminum pole  
Cobra Head  
LED