

sect 2 Chm 7/7/26
21075315

Inspections: Damaged Pole Report

Service Request: 26-00623367 Sector: _____ Gateway: _____ Primary: _____
Location on Service Request: 700 N. Howard St
Grid: 3010120 LLC: 7383

Descriptive Location and Comments:

Street: N. Howard St
Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____
Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
Direction: N/O _____ E/O _____ S/O _____ W/O ☒
Street or Landmark: W. Monument St

Condition of Pole:

Deteriorated _____
Missing ☒
Damaged _____
Arm/Fixture Missing _____
Other _____

Pole Size:

11'6" _____
12' ☒
25' _____
30' _____
40' _____
Other _____

Type of Pole:

Aluminum _____
Steel _____
Galvanized Steel _____
Fiberglass _____
Bolton Hill _____
Otterbein ☒
Homeland _____
Wooden _____
Other _____

Fixture Type:

Cobra Head _____
PMA _____
Otterbein ☒
Homeland _____
Bolton Hill _____
Victorian Acorn _____
Other _____

Lamp Type:

HPS Vapor ☒
Mercury Vapor _____
Metal Halide _____
LED _____
Other _____

Wattage:

100 _____
150 ☒
175 _____
200 _____
250 _____
400 _____
1000 _____

Arm:

6' _____
10' _____
15' _____
20' _____
Other _____

Arm Condition:

Damaged _____
Missing _____

Pedestal Base:

Yes ☒
No _____

Base Condition:

Bolts ☒
Wires ☒
Conduit ☒

Good

☒
☒
☒

Bad:

Base Type:

Metal ☒
Concrete _____

Date: 7/7/2026 Inspector's Signature: G. Crowder 8512

