

# Inspections: Damaged Pole Report

Service Request 26-00618223 Sector: \_\_\_\_\_ Gateway: \_\_\_\_\_ Primary: \_\_\_\_\_

Location on Service Request: 936 E. Eager St

Grid : 2010140 LLC: 7591

## Descriptive Location and Comments:

Street: Eager St

Side of Street: N/S ☒ E/S \_\_\_\_\_ S/S \_\_\_\_\_ W/S \_\_\_\_\_

Pole location: 1<sup>st</sup> ☒ 2<sup>nd</sup> \_\_\_\_\_ 3<sup>rd</sup> \_\_\_\_\_ 4<sup>th</sup> \_\_\_\_\_ 5<sup>th</sup> \_\_\_\_\_ 6<sup>th</sup> \_\_\_\_\_ Other \_\_\_\_\_

Direction : N/O \_\_\_\_\_ E/O \_\_\_\_\_ S/O \_\_\_\_\_ W/O ☒

Street or Landmark: Hartford Rd

## Condition of Pole:

Deteriorated \_\_\_\_\_  
Missing ☒  
Damaged \_\_\_\_\_  
Arm/Fixture Missing \_\_\_\_\_  
Other \_\_\_\_\_

## Pole Size :

11'6" \_\_\_\_\_  
12' \_\_\_\_\_  
25' \_\_\_\_\_  
30' ☒  
40' \_\_\_\_\_  
Other \_\_\_\_\_

## Type of Pole:

Aluminum \_\_\_\_\_  
Steel ☒  
Galvanized Steel \_\_\_\_\_  
Fiberglass \_\_\_\_\_  
Bolton Hill \_\_\_\_\_  
Otterbein \_\_\_\_\_  
Homeland \_\_\_\_\_  
Wooden \_\_\_\_\_  
Other \_\_\_\_\_

**NEEDS  
New  
Base**

**WORK ORDER #  
21075614**

## Fixture Type:

Cobra Head ☒  
PMA \_\_\_\_\_  
Otterbein \_\_\_\_\_  
Homeland \_\_\_\_\_  
Bolton Hill \_\_\_\_\_  
Victorian Acorn \_\_\_\_\_  
Other \_\_\_\_\_

## Lamp Type:

HPS Vapor \_\_\_\_\_  
Mercury Vapor \_\_\_\_\_  
Metal Halide \_\_\_\_\_  
LED ☒  
Other \_\_\_\_\_

## Wattage:

100 \_\_\_\_\_  
150 \_\_\_\_\_  
175 \_\_\_\_\_  
200 \_\_\_\_\_  
250 \_\_\_\_\_  
400 ☒  
1000 \_\_\_\_\_

## Arm:

6' ☒  
10' \_\_\_\_\_  
15' \_\_\_\_\_  
20' \_\_\_\_\_  
Other \_\_\_\_\_

## Arm Condition:

Damaged \_\_\_\_\_  
Missing ☒

## Pedestal Base:

Yes \_\_\_\_\_  
No ☒

## Base Condition:

Bolts ☒  
Wires ☒  
Conduit ☒

## Good

☒  
☒  
☒


## Bad:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

## Base Type:

Metal \_\_\_\_\_  
Concrete ☒

Date: 7/7/2026 Inspector's Signature: T. Blackman



30 Foot  
Steel  
pole  
Cobra Head  
LED