

Inspections: Damaged Pole Report

Service Request 26-00622492 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 1700 Fort Ave

Grid : 4030220 LLC: 7005

Descriptive Location and Comments:

Street: Fort Ave

Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____

Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O _____ W/O ☒

Street or Landmark: Nicholson St

Condition of Pole:

Deteriorated _____

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" _____

12' _____

25' _____

30' ☒

40' _____

Other _____

Type of Pole:

Aluminum ☒

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Work Order #
21075590

Fixture Type:

Cobra Head ☒

PMA _____

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor _____

Mercury Vapor _____

Metal Halide _____

LED ☒

Other _____

Wattage:

100 _____

150 _____

175 _____

200 _____

250 _____

400 ☒

1000 _____

Arm:

6' ☒

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing ☒

Pedestal Base:

Yes _____

No ☒

Base Condition:

Good

Bad:

Base Type:

Bolts ☒


Wires ☒

Conduit ☒

Metal _____

Concrete ☒

Date: 7/7/2026 Inspector's Signature: T. Blackman



30 Foot Aluminum
pole
Cobra Head
LED