

Inspections: Damaged Pole Report

Service Request 26-00607905 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 1630 Round Hill Rd

Grid : 2030210 LLC: 7202

Descriptive Location and Comments:

Street: Round Hill Rd

Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____

Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O ☒ S/O _____ W/O _____

Street or Landmark: Trivoli Ave

Condition of Pole:

Deteriorated _____

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" ☒

12' _____

25' _____

30' _____

40' _____

Other _____

Type of Pole:

Aluminum _____

Steel ☒

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

NEEDS
New
Base

Work order #
21061400

Fixture Type:

Cobra Head _____

PMA ☒

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor _____

Mercury Vapor _____

Metal Halide _____

LED ☒

Other _____

Wattage:

100 ☒

150 ☒

175 _____

200 _____

250 _____

400 _____

1000 _____

Arm:

6' _____

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes _____

No ☒

Base Condition:

Good

Bad:

Base Type:


Bolts
Wires
Conduit

☒
☒
☒

Metal
Concrete

☒

Date: 7/16/2026 Inspector's Signature: T. Blackman



Steel
PMA
HPS