

Inspections: Damaged Pole Report

Service Request: 26-00640669 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 3400 Elmora Ave

Grid : 2020330 , LLC: 7043

Descriptive Location and Comments:

Street: Elmora Ave

Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____

Pole location: 1" ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O _____ W/O ☒

Street or Landmark: Hoghtown

Condition of Pole:

Deteriorated ☐

Missing ☒

Damaged ☐

Arm/Fixture Missing ☐

Other _____

Pole Size :

11'6" ☒

12' ☐

25' ☐

30' ☐

40' ☐

Other _____

Type of Pole:

Aluminum ☒

Steel ☐

Galvanized Steel ☐

Fiberglass ☐

Bolton Hill ☐

Otterbein ☐

Homeland ☐

Wooden ☐

Other _____

NEEDS
New
Base

work order #
21048651

Fixture Type:

Cobra Head ☐

PMA ☒

Otterbein ☐

Homeland ☐

Bolton Hill ☐

Victorian Acorn ☐

Other _____

Lamp Type:

HPS Vapor ☐

Mercury Vapor ☐

Metal Halide ☐

LED ☒

Other ☐

Wattage:

100 ☐

150 ☒

175 ☐

200 ☐

250 ☐

400 ☐

1000 ☐

Arm:

6' ☐

10' ☐

15' ☐

20' ☐

Other ☐

Arm Condition:

Damaged ☐

Missing ☐

Pedestal Base:

Yes ☒
No ☐

Base Condition:

Bolts
Wires
Conduit


Good ☐

Bad: ☐

Base Type:

Metal ☐
Concrete ☐

Date: 7/14/2026 Inspector's Signature: T. Blackman



PMA
LED