

# Inspections: Damaged Pole Report

Service Request: 26-00643201 Sector: \_\_\_\_\_ Gateway: \_\_\_\_\_ Primary: \_\_\_\_\_  
 Location on Service Request: 1005 Brantley Ave  
 Grid : 3010220 LLC: 7133

## Descriptive Location and Comments:

Street: Brantley Ave  
 Side of Street: N/S \_\_\_\_\_ E/S ☒ S/S \_\_\_\_\_ W/S \_\_\_\_\_  
 Pole location: 1<sup>st</sup> ☒ 2<sup>nd</sup> \_\_\_\_\_ 3<sup>rd</sup> \_\_\_\_\_ 4<sup>th</sup> \_\_\_\_\_ 5<sup>th</sup> \_\_\_\_\_ 6<sup>th</sup> \_\_\_\_\_ Other \_\_\_\_\_  
 Direction : N/O \_\_\_\_\_ E/O \_\_\_\_\_ S/O ☒ W/O \_\_\_\_\_  
 Street or Landmark: N. Schneider St

## Condition of Pole:

## Pole Size :

## Type of Pole:

Deteriorated ☒

11'6" \_\_\_\_\_

Aluminum ☒

Missing ☒

12' \_\_\_\_\_

Steel \_\_\_\_\_

Damaged \_\_\_\_\_

25' ☒

Galvanized Steel \_\_\_\_\_

Arm/Fixture Missing \_\_\_\_\_

30' \_\_\_\_\_

Fiberglass \_\_\_\_\_

Other \_\_\_\_\_

40' \_\_\_\_\_

Bolton Hill \_\_\_\_\_

Other \_\_\_\_\_

Otterbein \_\_\_\_\_

Homeland \_\_\_\_\_

Wooden \_\_\_\_\_

Other \_\_\_\_\_

Need new base

## Fixture Type:

## Lamp Type:

## Wattage:

## Arm:

## Arm Condition:

Cobra Head ☒

HPS Vapor \_\_\_\_\_

100 \_\_\_\_\_

6' \_\_\_\_\_

Damaged \_\_\_\_\_

PMA \_\_\_\_\_

Mercury Vapor \_\_\_\_\_

150 \_\_\_\_\_

10' \_\_\_\_\_

Missing \_\_\_\_\_

Otterbein \_\_\_\_\_

Metal Halide \_\_\_\_\_

175 \_\_\_\_\_

15' \_\_\_\_\_

Homeland \_\_\_\_\_

LED ☒

200 \_\_\_\_\_

20' \_\_\_\_\_

Bolton Hill \_\_\_\_\_

Other \_\_\_\_\_

250 \_\_\_\_\_

Other \_\_\_\_\_

Victorian Acorn \_\_\_\_\_

400 ☒

Other \_\_\_\_\_

1000 \_\_\_\_\_

## Pedestal Base:

## Base Condition:

## Good

## Bad:

## Base Type:

Yes \_\_\_\_\_  
 No ☒

Bolts ☒  
 Wires ☒  
 Conduit ☒

Metal ☒  
 Concrete \_\_\_\_\_

Date: 7/14/2026 Inspector's Signature: E. Crowder 8512

HERE ARE THE KNOWN LOCATIONS FOR THIS LIGHT.

**DOWNED POLE & EXPOSED WIRES**


If you discover a downed streetlight pole, exposed electrical wires or any other hazardous situation, please call us immediately at **1-800-685-0123** with the closest address, intersection or landmark.

**NEVER TOUCH EXPOSED WIRES!**

**Pole Number**

30102207133

REPORT THIS LIGHT



**Service Request Summary Report**  
**26-00643201**  
Printed Date: Jul 14, 2026 - 7:22:09 AM

**Type:** BGE-StLight Pole Installation  
**Created By:** Debbie Womack  
**Service Request Owner:** BGE  
**Method Received:** Phone  
**SLA Detail:** 45 Business Days

**SR #:** 26-00643201  
**Priority:** Urgent  
**Status:** Open  
**Status Date:** Jul 14, 2026 7:22:03 AM  
**Created Date:** Jul 10, 2026 4:18:13 PM  
**Overdue on:** Sep 14, 2026 4:23:19 PM  
**Closed on:**

**Location:** 1005 BRANTLEY AVE, Baltimore City,  
21217

**Location Details:**  
**Description:**

**Service Questions**

| Questions | Answers |
|-----------|---------|
|-----------|---------|

**Contact Information**

| Name          | Address | Email              | Phones/Extensions |
|---------------|---------|--------------------|-------------------|
| tracy randall |         | puff1521@gmail.com | +1 (240) 614-8443 |

**Service Activities**

| Activity Name    | Status      | Assigned To | Outcome | Outcome Reason | Finish Date |
|------------------|-------------|-------------|---------|----------------|-------------|
| Assign inspector | Not Started |             |         |                |             |
| Service Response | Not Started |             |         |                |             |

**Resolution Questions**

| Service Activity | Resolution Question | Resolution Answer |
|------------------|---------------------|-------------------|
|------------------|---------------------|-------------------|

**Comments**

| Comment | Comment By | Created Date | Visibility |
|---------|------------|--------------|------------|
|---------|------------|--------------|------------|

**Related Child Service Requests**

**Related Parent Service Requests**

**Transfer Parent Service Requests**

TRM-StLight Damaged/Knocked Down/Rusted      26-00651376      Closed (Transferred)      1005 BRANTLEY AVE, Baltimore City, 21217

| Questions | Answers |
|-----------|---------|
|-----------|---------|

|                                                 |                  |
|-------------------------------------------------|------------------|
| Is the pole wooden or metal?                    | Metal            |
| What is the problem with the street light pole? | Leaning          |
| Where is the exact location of the pole?        | Front of address |
| Did you witness how the pole was damaged?       | Yes              |
| Please describe:                                |                  |