

Inspections: Damaged Pole Report

Service Request: 26-00659813 Gateway: _____ Primary: _____

Location on Service Request: 3604 WHITE Ave

Grid : 2040420 ILC: 7303

Descriptive Location and Comments:

Street: WHITE Ave

Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____

Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O ☒ S/O _____ W/O _____

Street or Landmark: Winthrop Ave

Condition of Pole:

Deteriorated ☒
Missing ☒
Damaged _____
Arm/Fixture Missing _____
Other _____

Pole Size :

11'6" ☒
12' _____
25' _____
30' _____
40' _____
Other _____

Type of Pole:

Aluminum ☒
Steel _____
Galvanized Steel _____
Fiberglass _____
Bolton Hill _____
Otterbein _____
Homeland _____
Wooden _____
Other _____

**NEEDS
New
Base**

Fixture Type:

Cobra Head _____
PMA ☒
Otterbein _____
Homeland _____
Bolton Hill _____
Victorian Acorn _____
Other _____

Lamp Type:

HPS Vapor _____
Mercury Vapor _____
Metal Halide ☒
LED _____
Other _____

Wattage:

100 _____
150 ☒
175 _____
200 _____
250 _____
400 _____
1000 _____

Arm:

6' _____
10' _____
15' _____
20' _____
Other _____

Arm Condition:

Damaged _____
Missing _____

Pedestal Base:

Yes _____
No _____


Base Condition:

Good _____
Bad: _____
Bolts _____
Wires _____
Conduit _____

Base Type:

Metal _____
Concrete _____

Date: 7/17/2026 Inspector's Signature: T. Blackman



PMIA
LED