

Check with Chris

Inspections: Damaged Pole Report

Service Request: 26-00660809 Sector: \_\_\_\_\_ Gateway: \_\_\_\_\_ Primary: \_\_\_\_\_

Location on Service Request: 701 Winans Way

Grid : 3010 520 LLC: 7013

Descriptive Location and Comments:

Street: Winans Way

Side of Street: N/S \_\_\_\_\_ E/S \_\_\_\_\_ S/S \_\_\_\_\_ W/S \_\_\_\_\_

Pole location: 1<sup>st</sup> \_\_\_\_\_ 2<sup>nd</sup> ☒ 3<sup>rd</sup> \_\_\_\_\_ 4<sup>th</sup> \_\_\_\_\_ 5<sup>th</sup> \_\_\_\_\_ 6<sup>th</sup> \_\_\_\_\_ Other \_\_\_\_\_

Direction : N/O \_\_\_\_\_ E/O \_\_\_\_\_ S/O \_\_\_\_\_ W/O \_\_\_\_\_

Street or Landmark: Hunting PL

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated \_\_\_\_\_

11'6" \_\_\_\_\_

Aluminum \_\_\_\_\_

Missing ☒

12' ☒

Steel \_\_\_\_\_

Damaged \_\_\_\_\_

25' \_\_\_\_\_

Galvanized Steel \_\_\_\_\_

Arm/Fixture Missing \_\_\_\_\_

30' \_\_\_\_\_

Fiberglass \_\_\_\_\_

Other \_\_\_\_\_

40' \_\_\_\_\_

Bolton Hill \_\_\_\_\_

Other \_\_\_\_\_

Otterbein \_\_\_\_\_

Homeland ☒

Wooden \_\_\_\_\_

Other \_\_\_\_\_

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head \_\_\_\_\_

HPS Vapor ☒

100 \_\_\_\_\_

6' \_\_\_\_\_

Damaged \_\_\_\_\_

PMA \_\_\_\_\_

Mercury Vapor \_\_\_\_\_

150 ☒

10' \_\_\_\_\_

Missing \_\_\_\_\_

Otterbein \_\_\_\_\_

Metal Halide \_\_\_\_\_

175 \_\_\_\_\_

15' \_\_\_\_\_

Homeland \_\_\_\_\_

LED \_\_\_\_\_

200 \_\_\_\_\_

20' \_\_\_\_\_

Bolton Hill \_\_\_\_\_

Other \_\_\_\_\_

250 \_\_\_\_\_

Other \_\_\_\_\_

Victorian Acorn ☒

400 \_\_\_\_\_

Other \_\_\_\_\_

1000 \_\_\_\_\_

Pedestal Base:

Base Condition:

Good

Bad:


Base Type:

Yes \_\_\_\_\_  
No ☒

Bolts ☒  
Wires ☒  
Conduit ☒

Metal ☒  
Concrete \_\_\_\_\_

Date: 7/21/2026 Inspector's Signature: G. Crowder 8512



701  
Winans Way 3010 520  
12 ft Admin: Acorn Fixtures  
150 watts

**Service Request Summary Report**  
**26-00660809**

Printed Date: Jul 21, 2026 - 7:59:09 AM

**Type:** BGE-StLight Pole Installation  
**Created By:** citizen Site Guest User  
**Service Request Owner:** BGE  
**Method Received:** API  
**SLA Detail:** 45 Business Days

**SR #:** 26-00660809  
**Priority:** Urgent  
**Status:** Open  
**Status Date:** Jul 21, 2026 7:59:06 AM  
**Created Date:** Jul 16, 2026 7:35:44 AM  
**Overdue on:** Sep 18, 2026 3:07:15 PM  
**Closed on:**

**Location:** 701 WINANS WAY, Baltimore City, 21229

**Location Details:**  
**Description:** Pole #7013

**Service Questions**

| Questions | Answers |
|-----------|---------|
|-----------|---------|

**Contact Information**

| Name           | Address | Email                          | Phones/Extensions |
|----------------|---------|--------------------------------|-------------------|
| Jason Mitchell |         | jtmitchell@amylestonegroup.com | +1 (510) 798-6439 |

**Service Activities**

| Activity Name    | Status      | Assigned To | Outcome | Outcome Reason | Finish Date |
|------------------|-------------|-------------|---------|----------------|-------------|
| Assign inspector | Not Started |             |         |                |             |
| Service Response | Not Started |             |         |                |             |

**Resolution Questions**

| Service Activity | Resolution Question | Resolution Answer |
|------------------|---------------------|-------------------|
|------------------|---------------------|-------------------|

**Comments**

| Comment | Comment By | Created Date | Visibility |
|---------|------------|--------------|------------|
|---------|------------|--------------|------------|

**Related Child Service Requests**

**Related Parent Service Requests**

**Transfer Parent Service Requests**

TRM-StLight Damaged/Knocked Down/Rusted      26-00666630      Closed (Transferred)      701 WINANS WAY, Baltimore City, 21229

| Questions                                       | Answers          |
|-------------------------------------------------|------------------|
| Is the pole wooden or metal?                    | Metal            |
| What is the problem with the street light pole? | Down             |
| Where is the exact location of the pole?        | Front of address |
| Did you witness how the pole was damaged?       | No               |