

Sent 2 Chs 7-21-26

Inspections: Damaged Pole Report

Service Request: 26-00664424 Sector: _____ Gateway: _____ Primary: _____
Location on Service Request: 1009 N. Fulton Ave
Grid: 1010'230 LLC: 7378

Descriptive Location and Comments:

Street: N. Fulton Ave
Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____
Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
Direction : N/O _____ E/O _____ S/O _____ W/O ☒
Street or Landmark: Mosher St

<u>Condition of Pole:</u>	<u>Pole Size :</u>	<u>Type of Pole:</u>
Deteriorated _____	11'6" _____	Aluminum ☒
Missing ☒	12' _____	Steel _____
Damaged _____	25' ☒	Galvanized Steel _____
Arm/Fixture Missing _____	30' _____	Fiberglass _____
Other _____	40' _____	Bolton Hill _____
	Other _____	Otterbein _____
		Homeland _____
		Wooden _____
		Other _____

<u>Fixture Type:</u>	<u>Lamp Type:</u>	<u>Wattage:</u>	<u>Arm:</u>	<u>Arm Condition:</u>
Cobra Head ☒	HPS Vapor _____	100 _____	6' ☒	Damaged _____
PMA _____	Mercury Vapor _____	150 _____	10' _____	Missing _____
Otterbein _____	Metal Halide ☒	175 _____	15' _____	
Homeland _____	LED ☒	200 _____	20' _____	
Bolton Hill _____	Other _____	250 ☒	Other _____	
Victorian Acorn _____		400 ☒		
Other _____		1000 _____		

<u>Pedestal Base:</u>	<u>Base Condition:</u>	<u>Good</u>	<u>Bad:</u>	<u>Base Type:</u>
Yes _____	Bolts ☒	☒	_____	Metal ☒
No ☒	Wires ☒	☒	_____	Concrete _____
	Conduit ☒	☒	_____	

Date: 7/21/2026 Inspector's Signature: G. Crowder 8512

N Bruce St N Bruce St

N Bruce St

N Bruce St

N Bruce St

1023 1023 1023 1023 1023

Sorry, we have no imagery here.

1020 1020 1020 1020 1020

Sorry, we have no imagery here.

1019 1019 1019 1019 1019

Sorry, we have no imagery here.

1018 1018 1018 1018 1018

Sorry, we have no imagery here.

N Fulton Ave

N Fulton Ave

N Fulton Ave

N Fulton Ave

N Fulton Ave

Sorry, we have no imagery here.

Sorry, we have no imagery here.

Sorry, we have no imagery here.

Sorry, we have no imagery here.

Sorry, we have no imagery here.

Riggs Ave

Mosher St

Kirby Ln

Service Request Summary Report
26-00664424

Printed Date: Jul 21, 2026 - 2:25:10 PM

Type: BGE-StLight Pole Installation
Created By: Ameer Davis
Service Request Owner: BGE
Method Received: Phone
SLA Detail: 45 Business Days

SR #: 26-00664424
Priority: Urgent
Status: Pending
Status Date: Jul 21, 2026 2:21:28 PM
Created Date: Jul 17, 2026 9:08:52 AM
Overdue on: Sep 21, 2026 3:58:06 PM
Closed on:

Location: 1009 N FULTON AVE, Baltimore City,
21217

Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		7/21/2026 2:21 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1020230
Assign inspector	LLC / POLE #	7378
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	25 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created by G Crowder 7-21-26	Gregory Crowder	7/21/2026 2:25 PM	Private
Assign inspector : missing pole report created by G	Gregory Crowder	7/21/2026 2:25 PM	Public