

Inspections: Damaged Pole Report

Service Request: 26-00686479 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 2301 W. Baltimore St
 Grid : 3010 340 LLC: 7256

Descriptive Location and Comments:

Street: W. Baltimore
 Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____
 Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O _____ S/O _____ W/O ☒
 Street or Landmark: S. Calverton Rd

Condition of Pole:

Deteriorated _____
 Missing ☒
 Damaged _____
 Arm/Fixture Missing _____
 Other _____

Pole Size :

11'6" _____
 12' _____
 25' _____
 30' ☒
 40' _____
 Other _____

Type of Pole:

Aluminum ☒
 Steel _____
 Galvanized Steel _____
 Fiberglass _____
 Bolton Hill _____
 Otterbein _____
 Homeland _____
 Wooden _____
 Other _____

Fixture Type:

Cobra Head ☒
 PMA _____
 Otterbein _____
 Homeland _____
 Bolton Hill _____
 Victorian Acorn _____
 Other _____

Lamp Type:

HPS Vapor _____
 Mercury Vapor _____
 Metal Halide _____
 LED ☒
 Other _____

Wattage:

100 _____
 150 _____
 175 _____
 200 _____
 250 _____
 400 ☒
 1000 _____

Arm:

6' _____
 10' _____
 15' _____
 20' _____
 Other _____

Arm Condition:

Damaged _____
 Missing _____

Pedestal Base:

Yes _____
 No ☒

Base Condition:

Bolts _____
 Wires ☒
 Conduit ☒

Good

☒
☒
☒

Bad:

Base Type:

Metal _____
 Concrete ☒

Date: 7/27/2026 Inspector's Signature: J. Crowder - 8512



Service Request Summary Report
26-00686479

Printed Date: Jul 28, 2026 - 7:28:00 AM

Type: BGE-StLight Pole Installation
Created By: Ashley Bailey
Service Request Owner: BGE
Method Received: Phone
SLA Detail: 45 Business Days

SR #: 26-00686479
Priority: Urgent
Status: Pending
Status Date: Jul 28, 2026 7:26:04 AM
Created Date: Jul 23, 2026 12:32:21 PM
Overdue on: Sep 28, 2026 7:57:35 AM
Closed on:

Location: 2301 W BALTIMORE ST, Baltimore City,
21223

Location Details:
Description: pole# 7256

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
jamie lopez		safety@mluisconstruction.com	+1 (202) 893-6410

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		7/28/2026 7:26 AM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	3010340
Assign inspector	LLC / POLE #	7256
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	30 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Concrete

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created by G Crowde7-27-26	Gregory Crowder	7/28/2026 7:27 AM	Private