

Inspections Damaged Pole Report

Service Request 26-00705208 Sector 712 Gateway So Hawaver St Primary 7501

Location on Service Request: 712 So Hawaver St

Grid : 3020120 LLC: 7501

Descriptive Location and Comments:

Street: _____

Side of Street: N/S _____ E/S _____ S/S _____ W/S _____

Pole location: 1st _____ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O _____ W/O _____

Street or Landmark: _____

Condition of Pole:

Deteriorated ☒

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" ☒

12' ☒

25' _____

30' _____

40' _____

Other _____

Type of Pole:

Aluminum _____

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein ☒

Homeland _____

Wooden _____

Other _____

Fixture Type:

Cobra Head _____

PMA ☒

Otterbein ☒

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor _____

Mercury Vapor _____

Metal Halide ☒

LED ☒

Other _____

Wattage:

100 ☒

150 ☒

175 ☒

200 _____

250 _____

400 _____

1000 _____

Arm:

6' _____

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes ☒

No _____

Base Condition:

Good ☒

Bad: _____

Bolts ☒

Wires ☒


Conduit ☒

Base Type:

Metal ☒

Concrete _____

Date: 7/30/2026 Inspector's Signature: T. Blackman



Other been pole
Other been fixture